

## LICENSEE EVENT REPORT

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	A	L	B	R	F	3	2	0	0	-	0	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4			5																							
7	8	9						14						15										25										26					30					57					58				
		LICENSEE CODE						LICENSE NUMBER																				LICENSE TYPE																									

CON'T

0 1 7 8 REPORT SOURCE L 6 0 5 0 0 0 2 9 6 7 0 3 3 1 8 2 8 0 4 2 9 8 2 9 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | During refueling, while performing daily source and background check of CAM 3-90-250  
0 3 | (reactor and turbine building vent monitor), the inlet sample line was discovered  
0 4 | disconnected. T.S.3.8.B.8 requires that these building vents be continuously  
0 5 | monitored. The T.S. requirements were not met for a period of up to 24 hours. Sample  
0 6 | line was verified connected during the last daily check. The CAM continued to monitor  
0 7 | the ambient atmosphere around the CAM. There are no redundant systems. There was  
0 8 | no effect on the health or safety of the public.

SYSTEM CODE M C 11		CAUSE CODE A 17		CAUSE SUBCODE X 13		COMP. SUBCODE Z 15		VALVE SUBCODE Z 16	
EVENT YEAR 8 2		SEQUENTIAL REPORT NO. 0 0 8		OCCURRENCE CODE 0 3		REPORT TYPE 1		REVISION NO. 0	
ACTION TAKEN X 13		FUTURE ACTION X 17		EFFECT ON PLANT Z 20		SHUTDOWN METHOD Z 21		HOURS 0 0 0 0	
ATTACHMENT SUBMITTED Y 23		NPRD-4 FORM SUB. N 24		PRIME COMP. SUPPLIER Z 25		COMPONENT MANUFACTURER Z 9 9 9 9		CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)	

1 0 | Apparent personnel error in disconnecting the sample line (personnel involved unknown).  
1 1 | The inlet sample line was immediately reconnected to the CAM. Warning signs \_\_\_\_\_  
1 2 | regarding sample lines will be placed on all CAMs by 5/19/82 as recurrence control.  
1 3 | \_\_\_\_\_  
1 4 | \_\_\_\_\_  
7 8 9 80

FACILITY STATUS			% POWER			OTHER STATUS			METHOD OF DISCOVERY			DISCOVERY DESCRIPTION		
1	5	H	28	0	0	0	29	NA	30	B	31	Radio chemical Lab Analyst Observation		
7	8	9	10	11	12	13	14	15	16	17	18	19	20	
ACTIVITY CONTENT			RELEASED OF RELEASE			AMOUNT OF ACTIVITY			LOCATION OF RELEASE					
1	5	Z	33	Z	14	NA	35	NA	36				80	
7	8	9	10	11	12	13	14	15	16	17	18	19	20	
PERSONNEL EXPOSURES			NUMBER			TYPE			DESCRIPTION					
1	7	0	0	0	37	Z	38	NA	39				80	
7	8	9	10	11	12	13	14	15	16	17	18	19	20	
PERSONNEL INJURIES			NUMBER			DESCRIPTION								
1	5	0	0	0	41	NA	42	NA	43				80	
7	8	9	10	11	12	13	14	15	16	17	18	19	20	
LOSS OF OR DAMAGE TO FACILITY			TYPE			DESCRIPTION								
1	5	Z	42	NA	43	NA	44	NA	45				80	
7	8	9	10	11	12	13	14	15	16	17	18	19	20	
PUBLICITY			ISSUED			DESCRIPTION						NRC USE ONLY		
2	5	N	44	NA	45	NA	46	NA	47				80	
7	8	9	10	11	12	13	14	15	16	17	18	19	20	

Id W. Norwood

PHONE: (205) 729-6846

017-928