

TENNESSEE VALLEY AUTHORITY NRC REGION
CHATTANOOGA, TENNESSEE 37401
ATLANTA, GEORGIA

1750 Chestnut Street Tower II

82 MAY 14 4 8: 56

May 10, 1982

Mr. James P. O'Reilly, Director
U.S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303


Dear Mr. O'Reilly:

TENNESSEE VALLEY AUTHORITY - BROWNS FERRY NUCLEAR PLANT UNIT 1 - DOCKET
NO. 50-259 - FACILITY OPERATING LICENSE DPR-33 - REPORTABLE OCCURRENCE
REPORT BFRO-50-259/82012 - REVISION 1

The enclosed report is a supplement to my letter dated February 23, 1982
concerning a residual heat removal minimum flow valve which failed to
close as required leading to declaring the affected low-pressure coolant
injection loop inoperable. This report is submitted in accordance with
Browns Ferry unit 1 Technical Specification 6.7.2.b(4).

Very truly yours,

TENNESSEE VALLEY AUTHORITY


H. J. Green
Director of Nuclear Power

Enclosure

cc (Enclosure):

Document Control Desk
U.S. Nuclear Regulatory Commission
Washington, DC 20555

Records Center
Institute of Nuclear Power Operations
1820 Water Place
Atlanta, Georgia 30339

NRC Inspector, Browns Ferry

OFFICIAL COPY

1822
11

8205210260 820510
PDR ADOCK 05000259
S PDR

An Equal Opportunity Employer