

CONTROL BLOCK:

--	--	--	--	--	--	--

 (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'TEVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0	7	
---	---	--

0	8
---	---

7 8

SYSTEM CODE
P C (11)

CAUSE CODE
E (12)

CAUSE SUBCODE
B (13)

COMPONENT CODE
V A L V E X (14)

COMP SUBCODE
D (15)

VALVE SUBCODE
D (16)

LER NO REPORT NUMBER		EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.	
17		8 2		0 3 5		0 3		L		0	
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED	
A 18 Z 19		Z 20		Z 21		0 0 0 0		N 22		N 23	
33		34		35		36		37		41	
NPR-4 FORM 518		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER							
Y 24		A 25		G 2 5 5							
42		43		44							

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | CS-486, A ONE INCH DIAPHRAGM VALVE WAS LEAKING DUE TO A DIAPHRAGM FAILURE. THE

1 1 | DIAPHRAGM, GRINNELL PART NO. WT-3675-3212-A2, WAS REPLACED.

1	2	
---	---	--

1	2	
---	---	--

1	1	
---	---	--

FACILITY STATUS (28) 1 5 E 26 % POWER 1 0 0 29 OTHER STATUS (30) NA METHOD OF DISCOVERY (31) B DISCOVERY DESCRIPTION (32) OPERATOR OBSERVATION

ACTIVITY CONTENT
RELEASED OF RELEASE

1 5 2 33 34 NA

AMOUNT OF ACTIVITY (35)

NA

LOCATION OF RELEASE (36)

NA

PERSONNEL EXPOSURES		NUMBER		TYPE		DESCRIPTION	
1	7	0	0	0	(37)	Z	(38) NA

		PERSONNEL INJURIES		DESCRIPTION		
1	2	3	4	5	6	7
0	0	0	0	40		NA

7	8	9	11	12
LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION				
I G	Z	(A)	NA	

7 2 3 10
PUBLICITY
ISSUED DESCRIPTION (45) 8205240323 820513
PDR ADOCK 05000316
S
NRC USE ONLY

7 8 9 10 PDR

NAME OF PREPARED DAVID G. WIZNER

PHONE: 616-465-5901