

RECEIVED  
NRC

# Washington Public Power Supply System

P.O. Box 968 3000 George Washington Way Richland, Washington 99352 (509) 372-5000  
Docket No. 50-397

May 10, 1982  
G02-82-430

REGION V

Mr. R. H. Engelken  
U.S. Nuclear Regulatory Commission  
Region V  
1450 Maria Lane, Suite 210  
Walnut Creek, California 94596

Subject: NUCLEAR PROJECT NO. 2  
10CFR50.55(e) REPORTABLE CONDITIONS #10, #58, #62, and #83  
DEFICIENCIES IN CONCRETE EXPANSION ANCHOR PROGRAM AND 10CFR50.55(e)  
REPORTABLE CONDITION #73 - DEFICIENCIES IN INSTALLED GROUT

## References: Expansion Anchor Deficiencies:

- a) Letter No. G02-79-120, dated July 2, 1979
- b) Letter No. G02-79-138, dated August 7, 1979
- c) Letter No. G02-81-245, dated August 18, 1981

## Grout Deficiencies:

- d) Letter No. G02-80-302, dated December 15, 1980
- e) Letter No. G02-82-143, dated February 5, 1982
- f) Letter No. G12-82-47, dated April 3, 1982

This is to inform you that WNP-2 has initiated the necessary actions to re-open 10CFR50.55(e) #10, Drilled in Concrete Inserts for Installation and Pipe Supports; #58, Quality Class I Raceway Support Anchors; #62, Improper Anchor Bolt Installation - Contract 216; #83, Installation of Concrete Anchors; and #73, Concrete/Grouting - Contract 215, as requested in reference f).

Interim Reports on the above items will be provided by July 1, 1982. All subsequent reports will be provided on a quarterly basis until a final report is filed.

If there are any questions concerning this matter, please contact Roger Johnson at (509) 377-2501, extension 2712.

*R. G. Matlock*  
R. G. Matlock  
Program Director, WNP-2

LCF/kd

cc: W.S. Chin, BPA - Site  
R. A. Feil, NRC Resident Inspector - Site  
A. Forrest, Burns and Roe - HAPO  
N.D. Lewis, NRC  
J. Plunkett, NUS Corp.  
R.E. Snaith, Burns and Roe - NY  
V. Stello, NRC

8205250201 820510  
PDR ADOCK 05000397  
S PDR

1E27  
5/10  
82-98