

No. 3-82-03/03L-0

The following LER describes an operator error in replacing a circuit breaker after a maintenance block. The applicable Technical Specification is 4.5.A.2.

7 8 9 TO
PUBLICATION
ISSUED DESCRIPTION (45) 82052600295 NRC USE ONLY
2 0 N 44 68 69 80
10
NAME OF PREPARED M. J. Cooney PHONE (215) 841-5020

8205260029 5

NRC USE ONLY

PHONE: (215) 841-5020