

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

400 Chestnut Street Tower II

May 24, 1982

BLRD-50-438/81-47

BLRD-50-439/81-50

U.S. Nuclear Regulatory Commission

Region II

Attn: Mr. James P. O'Reilly, Regional Administrator

101 Marietta Street, Suite 3100

Atlanta, Georgia 30303

Dear Mr. O'Reilly:


BELLEFONTE NUCLEAR PLANT UNITS 1 AND 2 - TOLERANCE FOR TUBULAR STEEL CABLE
TRAY HANGERS - BLRD-50-438/81-47, BLRD-50-439/81-50 - FIFTH INTERIM
REPORT

The subject deficiency was initially reported to NRC-OIE Inspector
R. V. Crlenjak on July 16, 1981 in accordance with 10 CFR 50.55(e) as
NCR 1478. This was followed by our interim reports dated August 14 and
November 9, 1981 and January 21 and April 14, 1982. TVA is still
evaluating the cause of this deficiency. This matter will be resolved,
and proper actions to prevent recurrence will be identified in the next
report. We expect to submit our next report by July 26, 1982.

If you have any questions concerning this matter, please get in touch with
R. H. Shell at FTS 858-2688.

Very truly yours,

TENNESSEE VALLEY AUTHORITY


L. M. Mills, Manager
Nuclear Licensing

cc: Mr. Richard C. DeYoung, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

8206070135 820524
PDR ADDCK 05000438
S PDR

OFFICIAL COPY

IE 27

1/0