




LOUISIANA
POWER & LIGHT

142 DELARONDE STREET
P. O. BOX 6008 • NEW ORLEANS, LOUISIANA 70174 • (504) 366-2345

June 3, 1982



G. D. McLENDON
Senior Vice President

W3K-82-0315
Q-3-A35.07.45

Mr. John T. Collins, Regional Administrator, Region IV
U. S. Nuclear Regulatory Commission
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76012

Subject: Waterford SES Unit No. 3
Docket No. 50-382
Significant Construction Deficiency No. 45
"AKR 50 Relay Bell Switch Mounting Failure"
Second Interim Report

Reference: 1) LP&L Letter W3K-82-0080 to USNRC dated 2/11/82
2) Telecon R. G. Bennett (LP&L) to L. Martin (NRC), 6/1/82

Dear Mr. Collins:

The referenced letter submitted an interim report to the USNRC in which LP&L committed to providing a final report on Significant Construction Deficiency No. 45 by May 28, 1982.

The materials required are presently on site in the LP&L Warehouse and awaiting installation. Most of the devices in question are released to LP&L and are energized, making coordination of repair or replacement difficult. We anticipate a completion date of June 30, 1982 at which time a final report will be issued.

If you have any questions, please let us know.

Very truly yours,

G. D. McLENDON

GDMcL/LLB/grf

- cc: 1) Director
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555
- 2) Director
Office of Management
Information and Program Control
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

IE-27