



GULF STATES UTILITIES COMPANY

POST OFFICE BOX 2951 • BEAUMONT, TEXAS 77704


AREA CODE 713 838-6631

June 2, 1982
RBG-12,751
File Nos. G9.5, G9.25.1.1

Mr. John T. Collins, Regional Administrator
U. S. Nuclear Regulatory Commission
Region IV, Office of Inspection and Enforcement
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76011

Dear Mr. Collins:

River Bend Station Unit 1
Docket No. 50-458
Interim Report/DR-47



On April 30, 1982, Gulf States Utilities Company (GSU) notified your office of a condition potentially reportable under 10CFR50.55(e) concerning arc strikes found on Graver shop-fabricated drywell penetrations. GSU has not completed its investigation at this time. An interim or final status report will be provided by July 23, 1982.

Sincerely,

William J. Booker
for J. E. Booker
Manager-Engineering & Licensing
River Bend Nuclear Group

JEB/RJK/kt

cc: Director of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

IE-27