

LICENSEE EVENT REPORT

CONTROL BLOCK:

--	--	--	--	--	--

 (1)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	N	J	S	G	S	2	2	0	0	-	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4			5
7	8	LICENSEE CODE						14	LICENSE NUMBER										25	LICENSE TYPE					30	57 CAT 58			

CON'T

0 1 7 8

REPORT SOURCE L 6 0 5 0 0 0 3 1 1 7 0 3 0 7 8 2 8 0 3 3 1 8 2 9

60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | On March 7, 1982 an undervoltage condition in No. 2A Safeguards Equipment Control

0 3 | (SEC) Cabinet caused a Mode 1 No. 2A SEC actuation. No. 2A Diesel Generator started

0 4 | and all safety-related loads were energized. The SEC actuation could not be reset

0 5 | and No. 2A SEC cabinet was de-energized. At 0830 hours Limiting Condition for

0 6 | Operation 3.3.2.b Action 13 was entered.

0 7 |

0 8 |

7 8 9 80

0	9	SYSTEM CODE		I	B	11	CAUSE CODE		E	12	CAUSE SUBCODE		G	13	COMPONENT CODE				I	N	S	T	R	U	14	COMP. SUBCODE		X	15	VALVE SUBCODE		Z	16							
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47
LER/RO REPORT NUMBER		EVENT YEAR		SEQUENCE REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.		ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER												
17		8 2		0 1 9		0 3		L		0		C		Z		Z		Z		0 0 0 0		Y		Y		N		V 1 3 2												

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 The cause of the SEC actuation was failure of the Card File Assembly in No. 2A SEC
1 1 Cabinet. No. 2A Diesel Generator and all electrical loads that started as a result of
1 2 the SEC actuation were secured. A new Card File Assembly was installed in No. 2A
1 3 SEC Cabinet and Surveillance Procedure M3B was satisfactorily performed. No. 2A SEC
1 4 was declared operable, and at 1146 hours, March 7, 1982 Limiting Condition for Oper-
7 8 9 ation 3.3.2.b Action 13 was terminated.

FACILITY STATUS				% POWER		OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION	
1	5	E	28	0	9	9	29	NA	A	31	Operator Observation

ACTIVITY CONTENT
RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36)

1 6 2 33 2 34 NA NA

7 8 9 10 11 44 45 80

PERSONNEL EXPOSURES		NUMBER		TYPE	DESCRIPTION
1	7	0	0	0	NA

PERSONNEL INJURIES		DESCRIPTION	
NUMBER			
1	8	0	0
0	0	0	40
			NA

7		8		9		11		12		80		
LOSS OF OR DAMAGE TO FACILITY						(43)						
TYPE		DESCRIPTION										
1	9	Z	(42)	NA								

7 8 9 10 80
 PUBLICITY
 ISSUED DESCRIPTION (45) 8204160233 820331
 PDR ADOCK 05000311 NRC USE ONLY
 2 0 N (44) NA S PDR
 7 8 9 10 68 69 80

NAME OF PREPARER R. Frahm

PHONE: 609-935-0998