

CONTROL BLOCK: _____ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'T

0	1
---	---

REPORT SOURCE

L	6	0	5	0	0	0	3	6	1	7	0	3	0	8	8	2	8	0	4	0	7	8	2	9
---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---

60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

02 | On March 8, 1982 at 1205, with core alterations in progress, operations

03 | personnel discovered that Containment Purge Isolation System (CPIS)

04 | operability had not been demonstrated within 7 days as required by

05 | Technical Specification 4.99. Core alterations were halted for

06 | approximately two hours while CPIS operability was demonstrated. There

07 | was no effect on public health and safety as a result of this incident.

[illegible]

CPIS testing was not conducted at the scheduled time as purge valves were out of service to permit valve seat cleaning. Purge valves were returned to service without verifying CPIS operability. Operating personnel have been instructed to log all incomplete surveillance tests and to identify the tests as prerequisite to returning equipment to service.

FACILITY STATUS (1) 5 (2) B (28) % POWER (3) 0 (4) 0 (5) 0 (6) 0 (29) NA OTHER STATUS (30) METHOD OF DISCOVERY (31) B Operator Observation (32) DISCOVERY DESCRIPTION (32)

ACTIVITY CONTENT (1) 6 (2) 8 (3) 3 (4) 3 (5) 4 AMOUNT OF ACTIVITY (35) NA LOCATION OF RELEASE (36) NA

PERSONNEL EXPOSURES (1) 7 (2) 0 (3) 0 (4) 0 (5) 3 (6) 3 (7) 3 NA (39) DESCRIPTION (39)

PERSONNEL INJURIES (1) 8 (2) 0 (3) 0 (4) 0 (5) 4 (6) 4 NA (41) DESCRIPTION (41)

LOSS OF OR DAMAGE TO FACILITY (1) 9 (2) 8 (3) 4 (4) 4 (5) 4 NA (43) DESCRIPTION (43) 8204160295 820407 PDR ADOCK 05000361 PDR

PUBLICITY (1) 10 (2) 8 (3) 4 (4) 4 (5) 4 NA (45) DESCRIPTION (45) NRC USE ONLY

NAME OF PERSON H.B. Ray

(714) 492-7700