

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

400 Chestnut Street Tower II

April 1, 1982

2 APR 5 411:04

HTRD-50-518, -519, -520, -521/81-04  
PBRD-50-553/81-06, -554/81-04

U.S. Nuclear Regulatory Commission  
Region II  
ATTN: James P. O'Reilly, Regional Administrator  
101 Marietta Street, Suite 3100  
Atlanta, Georgia 30303



Dear Mr. O'Reilly:

HARTSVILLE AND PHIPPS BEND NUCLEAR PLANTS - COMPLETION OF AS-BUILT  
DRAWINGS - HTRD-50-518, -519, -520, -521/81-04 AND  
PBRD-50-553/81-06, -554/81-04

The subject deficiencies were initially reported to NRC-OIE, Region II, Inspector R. W. Wright on January 22, 1981, as NCR's HTN-M80-10 and PBN-M80-10, deficiency Nos. 13, 14, and 21. The final reports on deficiency Nos. 13 and 21 were submitted on April 1, 1981 and January 18, 1982. In compliance with paragraph 50.55(e) of 10 CFR Part 50, this letter constitutes our fifth interim report on deficiency No. 14.

TVA is still in the process of evaluating deficiency No. 14. We anticipate transmitting our next report on or before July 15, 1982. If you have any questions, please call Jim Domer at FTS 858-2725.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

L. M. Mills, Manager  
Nuclear Regulation and Safety

cc: Mr. R. C. DeYoung, Director  
Office of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
Washington, DC 20555

OFFICIAL COPY

IE 27  
1/0