

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401
400 Chestnut Street Tower II

April 2, 1982

HTRD-50-518/81-14, -520/81-12
PBRD-50-553/81-15

U.S. Nuclear Regulatory Commission
Region II
ATTN: James P. O'Reilly, Regional Administrator
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303



Dear Mr. O'Reilly:

HARTSVILLE AND PHIPPS BEND NUCLEAR PLANTS - REPORTABLE DEFICIENCIES -
REVIEW OF PURCHASE REQUEST FORMS INITIATED BY CONSTRUCTION -HTRD-50-
518/81-14, -520/81-12 - PBRD-50-553/81-15

The subject deficiencies were initially reported to NRC-OIE, Region II, Inspector P. A. Taylor on May 20, 1981 as NCR's HTAHPP81-01 and PBNHPP81-01. TVA submitted the first, second, third, and fourth interim reports on June 19, August 28, and November 6, 1981, and February 16, 1982, respectively. In compliance with paragraph 50.55(e) of 10 CFR Part 50, this letter constitutes the fifth interim report on the subject deficiencies. TVA is still in the process of analyzing the deficiencies. We anticipate transmitting the next report on or before July 15, 1982. If you have any questions, please call Jim Domer at FTS 858-2725.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

L. M. Mills, Manager
Nuclear Regulation and Safety

cc: Mr. R. C. DeYoung, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

OFFICIAL COPY

IE, 27
1/6