



Carolina Power & Light Company


Telecopied 3-26-82 jb

Brunswick Steam Electric Plant
P. O. Box 10429
Southport, NC 28461-0429

March 26, 1982

FILE: B09-13516
SERIAL: BSEP/82-639

Mr. James P. O'Reilly, Director
U. S. Nuclear Regulatory Commission
Region II, Suite 3100
101 Marietta Street N.W.
Atlanta, GA 30303



BRUNSWICK STEAM ELECTRIC PLANT, UNIT NO. 1
DOCKET NO. 50-325
LICENSE NO. DPR-71

CONFIRMATION FACSIMILE OF AN IMMEDIATELY REPORTABLE EVENT (1-82-41)

Dear Mr. O'Reilly:

This confirms the conversation at 1720 on March 25, 1982, between Mr. P. T. McNeill, Shift Operating Supervisor, and Mr. Al Morrongiello, NRC Operations Center, concerning an immediately reportable event per Technical Specification 6.9.1.8f.

At 1630 on March 25, 1982, an auxiliary operator performing a routine tour of the Unit No. 1 Reactor Building found the motor cooler isolation valves to the 1B and 1D RHR service water pumps open with the pumps not running, indicating that the power supply to these valves was isolated. An investigation determined that circuit breaker 19, which supplies power to these valves and supplies power to the B loop RHR service water suction low pressure pump switches, was found in the tripped position. This breaker being open prevents the 1B or 1D RHR service water pump from starting. The breaker was immediately reset and the system restored to normal service. An investigation into this event is in progress and results will be reported in the fourteen-day report.

Very truly yours,

C. R. Dietz
C. R. Dietz, General Manager
Brunswick Steam Electric Plant

RMP/gvc

Enclosure

cc: Mr. V. Stello, Jr.

OFFICIAL COPY

Teas