



March 31, 1982

PNS-LI-82-128



Mr. James P. O'Reilly
Regional Administrator, Region II
U.S. Nuclear Regulatory Commission
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

REPORTABLE OCCURRENCE 250-82-03
TURKEY POINT UNIT 3
DATE OF OCCURRENCE: MARCH 1, 1982
TECHNICAL SPECIFICATION 6.9.2.b
CRACKED WELD

The attached Licensee Event Report is being submitted in accordance with Technical Specification 6.9 to provide 30 day notification of the subject occurrence.

Very truly yours,

J. W. Williams, Jr.
Vice President
Nuclear Energy

PLP/cab

Attachment

cc: Director, Office of Inspection and Enforcement (30)
Harold F. Reis, Esquire
File 933.1 TP

8204160497 820331
PDR ADOCK 05000250
S PDR

OFFICIAL COPY

1222
11

PEOPLE SERVING PEOPLE