

DUKE POWER COMPANY

POWER BUILDING

422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28242

WILLIAM O. PARKER, JR.
VICE PRESIDENT
STEAM PRODUCTION

March 19, 1982

TELEPHONE: AREA 704
373-4083

Mr. James P. O'Reilly, Regional Administrator
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303


Re: Oconee Nuclear Station
Docket No. 50-269



Dear Mr. O'Reilly:

On March 6, 1982, your office was informed that the 1B steam generator had an indicated tube leak of 0.08 gal/min. This constitutes an abnormal degradation of the reactor coolant pressure boundary. Reportable Occurrence Report RO-269/82-06 providing details of this incident was to have been submitted to you by March 19, 1982, pursuant to Technical Specification 6.6.2.1.a(3). However, the investigation of this incident and the preparation of a report are incomplete at this time. It is expected that the investigation and report will be completed, reviewed, and submitted to you no later than April 2, 1982.

Very truly yours,


William O. Parker, Jr.

JFK/php

cc: Director
Office of Management & Program Analysis
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Mr. W. T. Orders
NRC Resident Inspector
Oconee Nuclear Station

Records Center
Institute of Nuclear Power Operations
1820 Water Place
Atlanta, Georgia 30339

Mr. Philip C. Wagner
Office of Nuclear Reactor Regulation
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

8204160539 820319
PDR ADOCK 05000269
S PDR

OFFICIAL COPY

IE 22
1/0