

USNRC REGION II
ATLANTA, GE

DUKE POWER COMPANY

POWER BUILDING

422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28242

02 APR 12 10:47

April 7, 1982

WILLIAM O. PARKER, JR.
VICE PRESIDENT
STEAM PRODUCTION

TELEPHONE: AREA 704
373-4083


Mr. James P. O'Reilly, Regional Administrator
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Re: McGuire Nuclear Station Unit 1
Docket No. 50-369

Dear Mr. O'Reilly:

Please find attached Reportable Occurrence Report RO-369/82-21. This report concerns T.S.4.5.1.1.1(d-1), "Each cold leg injection accumulator shall be demonstrated operable:...d. At least once per 18 months by verifying that each...valve opens automatically...i. When an actual or a simulated RCS pressure signal exceeds the P-11 (pressurizer pressure block of safety injection) setpoint". This incident was considered to be of no significance with respect to the health and safety of the public.

Very truly yours,



William O. Parker, Jr.

PBN/jfw
Attachment

cc: Director
Office of Management and Program Analysis
U. S. Nuclear Regulatory Commission
Washington, D. C.

Records Center
Institute of Nuclear Power Operations
1820 Water Place
Atlanta, Georgia 30339

Mr. P. R. Bemis
Senior Resident Inspector-NRC
McGuire Nuclear Station



OFFICIAL COPY

1822
S/