



THE CLEVELAND ELECTRIC ILLUMINATING COMPANY

P.O. BOX 5000 ■ CLEVELAND, OHIO 44101 ■ TELEPHONE (216) 622-9800 ■ ILLUMINATING BLDG. ■ 55 PUBLIC SQUARE

Dalwyn R. Davidson

VICE PRESIDENT
SYSTEM ENGINEERING AND CONSTRUCTION

Serving The Best Location in the Nation

James G. Keppler
Director, Region III
Office of Inspection and Enforcement
US Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60137

April 15, 1982



PRINCIPAL STAFF			
✓ DIR	JAC	PAIS	
D/D		PAO	
A/D		SLO	
✓ DR&PI			
DESTI			
DEP&OS		File	JAC

RE: Perry Nuclear Power Plant
Docket Nos. 50-440 and 50-441
Repairs to Motor Control
Centers (RDC 17(80))

Dear Mr. Keppler:

This letter constitutes a revision to our letter dated November 25, 1981 regarding the repair of Cutler-Hammer Motor Control Centers. In that letter the scheduled completion date of repairs, as outlined in our final report dated March 9, 1981, was changed from June 1, 1981 to April 1, 1982. As a result of our continued investigation, this date is again in need of revision.

Further inspections of all Cutler-Hammer starter units, not previously determined to be deficient, revealed problems on eleven additional starters. Eight starters contained unqualified wire and seven contained improper terminal blocks. These additional deficiencies have been documented on either Nonconformance Reports or Deficiency Reports.

In regard to the replacement of Bus Bar Splice Plate bolts, this work is proceeding. Originally only one motor control center was identified as having defective splice plate bolts. As part of the disposition to this nonconforming condition, splice plate bolts on all motor control centers were to be replaced. This work has been completed on all but two 125VDC motor control centers. However, in order to aid in the tracking of documentation requirements, additional nonconformance reports are being generated to clarify the specific motor control centers involved.

The replacement of wiring, terminal blocks and splice plate bolts is now scheduled for completion on September 15, 1982.

8204220104 820415
PDR ADOCK 05000440
S PDR

cc: Mr. M. L. Gildner
NRC Site

Director, Office of
Inspection and Enforcement
US Nuclear Regulatory Commission
Washington, DC 20555

US Nuclear Regulatory Commission
c/o Document Management Branch
Washington, DC 20555

Sincerely,

Dalwyn R. Davidson

Dalwyn R. Davidson
Vice President
System Engineering and Construction

APR 19 1982

IE 27/16