

# LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

LICENSEE CODE: M I D C C 1  
LICENSE NUMBER: 0 0 - 0 0 0 0 0 0 - 0 0  
LICENSE TYPE: 4 1 1 1 1  
CAT: 5

REPORT SOURCE: L  
DOCKET NUMBER: 0 5 0 0 0 3 1 5  
EVENT DATE: 0 3 2 0 8 2  
REPORT DATE: 0 4 1 6 3 2

## EVENT DESCRIPTION AND PROBABLE CONSEQUENCES

DURING NORMAL OPERATION NO. 4 S/G STOP VALVE DUMP VALVES, MRV-241 AND MRV-242 WERE REMOVED FROM SERVICE TO REPAIR SEAT LEAKAGE. THIS CONDITION PLACED THE NO. 4 STEAM GENERATOR STOP VALVE IN A LESS CONSERVATIVE CONFIGURATION THAN THAN REQUIRED BY T.S. 3.7.1.5. DURING EACH REPAIR THE REDUNDANT VALVE REMAINED OPERABLE. ACTION REQUIREMENTS WERE MET AND PUBLIC HEALTH AND SAFETY WERE NOT AFFECTED. SIMILAR OCCURRENCES: DOCKET 050-316; RO'S 81-030, 81-068, 81-069, AND 81-070.

SYSTEM CODE: H B  
CAUSE CODE: E  
CAUSE SUBCODE: B  
COMPONENT CODE: V A L V E X  
COMP. SUBCODE: P  
VALVE SUBCODE: D  
LER NO. REPORT NUMBER: 8 2  
EVENT YEAR: 8 2  
SEQUENTIAL REPORT NO.: 0 1 7  
OCCURRENCE CODE: 0 3  
REPORT TYPE: L  
REVISION NO.: 0  
ACTION TAKEN: A  
FUTURE ACTION: Z  
EFFECT ON PLANT: Z  
SHUTDOWN METHOD: Z  
HOURS: 0 0 0 0  
ATTACHMENT SUBMITTED: N  
NPR-4 FORM SUB.: N  
PRIME COMP. SUPPLIER: A  
COMPONENT MANUFACTURER: F 1 2 7

## CAUSE DESCRIPTION AND CORRECTIVE ACTIONS

THE VALVES WERE REMOVED FROM SERVICE TO CORRECT SEAT LEAKAGE. THE STEM, DISC, SEAT RING AND GASKETS WERE REPLACED IN EACH OF THE FISHER STYLE 657 EAS VALVES. SEAT LEAKAGE OF VALVES IN THIS TYPE OF SERVICE IS NOT TOTALLY PREVENTABLE. NO FURTHER ACTION IS PLANNED.

FACILITY STATUS: E  
% POWER: 1 0 0  
OTHER STATUS: NA  
METHOD OF DISCOVERY: A  
DISCOVERY DESCRIPTION: OPERATOR OBSERVATION

ACTIVITY CONTENT: Z  
AMOUNT OF ACTIVITY: NA  
LOCATION OF RELEASE: NA

PERSONNEL EXPOSURES NUMBER: 0 0 0  
TYPE: Z  
DESCRIPTION: NA

PERSONNEL INJURIES NUMBER: 0 0 0  
DESCRIPTION: NA

LOSS OF OR DAMAGE TO FACILITY TYPE: Z  
DESCRIPTION: NA

PUBLICITY ISSUED DESCRIPTION: NA

8204220403 820416  
PDR ADDCK 05000315  
S PDR

NAME OF PREPAPER: ROBERT H. PIEHL

PHONE: 616-465-5901