



RICHARD P. CROUSE
Vice President
Nuclear
(419) 259-5221

Docket No. 50-346

License No. NPF-3

Serial No. 1-250

February 26, 1982

Mr. R. L. Spessard, Director
Division of Resident and Project Inspection
U. S. Nuclear Regulatory Commission
Region III
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Dear Mr. Spessard:

This letter is to identify ongoing activity related to your December 15, 1981 letter containing report 50-346/81-18. This deals with the violation of Appendix A Technical Specification Section 2.2.1 (Table 2.2-1). In addition to the corrective action taken in our letter of January 14, 1982 (Serial No. 1-239), Toledo Edison is providing an independent review of the Safety Features Actuation Systems (SFAS) Instrument Calibration Procedures. The intent of this review is aimed at verifying SFAS instrument string accuracies. This will assure compliance with the Davis-Besse Technical Specification requirements and the appropriate Safety Analysis.

This review is to be completed by March 31, 1982.

Very truly yours,

RPC:RFP:rs

cc: DB-1 NRC Resident Inspector

8204260 244