



Docket No. 50-346

License No. NPF-3

Serial No. 1-255

March 23, 1982

RICHARD P. CROUSE  
Vice President  
Nuclear  
(419) 259-5221

Mr. R. L. Spessard, Director  
Division of Resident and Project Inspection  
United States Nuclear Regulatory Commission  
Region III  
799 Roosevelt Road  
Glen Ellyn, Illinois 60137

PRINCIPAL STAFF			
DIR		ESIS	
D/D		PAO	
A/D		SLO	
DR&PI			
DEMTI			
DEMOG		File	<i>lan</i>

Dear Mr. Spessard:

This letter is written in response to a telephone conversation between Region III and Toledo Edison regarding instrument calibration procedures for the Davis-Besse Nuclear Power Station Unit 1. In addition to providing an independent review of the Safety Features Actuation Systems (SFAS) Instrument Calibration Procedures (Serial No. 1-250), Toledo Edison will also provide an independent review of the Reactor Protection System (RPS) Instrument Calibration Procedures by August 31, 1982, and of the Steam and Feedwater Rupture Control System (SFRCS) Instrument Calibration Procedures by October 31, 1982. The intent of these reviews is to verify RPS and SFRCS instrument string accuracies. This will ensure compliance with the Davis-Besse Technical Specification requirements and the appropriate Safety Analysis.

Very truly yours,

RPC:RFP:rs

cc: DB-1 NRC Resident Inspector

8204260 248

MAR 25 1982