




GULF STATES UTILITIES COMPANY

POST OFFICE BOX 2951 • BEAUMONT, TEXAS 77704

AREA CODE 713 838-6631

June 3, 1982
RBG-12,749
File Nos. G9.5, G9.25.1.1

Mr. John T. Collins, Regional Administrator
U. S. Nuclear Regulatory Commission
Region IV, Office of Inspection and Enforcement
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76011



Dear Mr. Collins:

River Bend Station Unit 1
Docket No. 50-458
Interim Report/DR-50

On May 4, 1982, Gulf States Utilities Company (GSU) notified your office of a condition potentially reportable under 10CFR50.55(e) concerning the failure of Power Strut model PS-809 welded support assemblies. GSU has not completed its investigation at this time. An interim or final status report will be provided by July 23, 1982.

Sincerely,

J. E. Booker
Manager-Engineering & Licensing
River Bend Nuclear Group

WYR/K
JEB/RJK/kt

cc: Director of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

IE 27

8206110124 820603
PLR ADOCK 05000458
S PDR