

DUKE POWER COMPANY  
POWER BUILDING  
ATLANTA, GEORGIA

422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28242

82 JUN 4 AIO: 24

WILLIAM O. PARKER, JR.  
VICE PRESIDENT  
STEAM PRODUCTION

May 28, 1982

TELEPHONE: AREA 704  
373-4083


Mr. James P. O'Reilly, Regional Administrator  
U. S. Nuclear Regulatory Commission  
Region II  
101 Marietta Street, Suite 3100  
Atlanta, Georgia 30303

Re: Catawba Nuclear Station  
Units 1 and 2  
Docket Nos. 50-413 and 50-414

Dear Mr. O'Reilly:

Significant Deficiency Report SD 413-414/82-12 concerning the location of studs in embedded plates was to be sent on or before June 4, 1982. It has been determined that all of the necessary information will not be available at that time. The report will be sent by July 16, 1982.

Very truly yours,



William O. Parker, Jr.

RWO/php

cc: Director  
Office of Inspection and Enforcement  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

Mr. P. K. Van Doorn  
NRC Resident Inspector  
Catawba Nuclear Station

Mr. Robert Guild, Esq.  
Attorney-at-Law  
314 Pall Mall  
Columbia, South Carolina 29201

Palmetto Alliance  
2135½ Devine Street  
Columbia, South Carolina 29205

EX-104 COPY

TE 27

8206110248 820528  
PDR ADOCK 05000413  
S PDR