



INDIANA & MICHIGAN ELECTRIC COMPANY

DONALD C. COOK NUCLEAR PLANT
P.O. Box 458, Bridgman, Michigan 49106
(616) 465-5901

June 4, 1982

Mr. J. G. Keppler, Regional Director
Office of Inspection and Enforcement
United States Nuclear Regulatory Commission
Region III
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Operating License DPR-74
Docket No. 50-316

Dear Mr. Keppler:

This is to confirm our verbal report to Mr. E. R. Swanson, NRC Region III Inspector, on June 3, 1982 at approximately 1800 hours, at which time we reported that field inspection of Panel VCC 2ABV-A showed this panel to have mounting details different from that required by the drawings. Evaluation of these mountings confirmed the necessity for modification for seismic consideration. Temporary lateral bracing was installed the evening of June 3. Permanent modification in accordance with RFC 02-2603 was approved by a temporary waiver letter, also June 3, 1982. Installation of the permanent modification is in progress at this time.

A complete report will be submitted within fourteen (14) days.

Sincerely,


W. G. Smith, Jr.
Plant Manager

WGS:frb

cc: J. E. Dolan
R. S. Hunter
R. W. Jurgensen
R. F. Kroeger
K. J. Vehstedt
E. Swanson/N. DuBry RO:III
R. C. Callen MPSC
J. M. Hennigan
W. Lavallee EPRI
PNSRC
G. Charnoff, Esq.
J. F. Stietzel
E. L. Townley
Dir., IE (30 copies)
Dir., MDC (2 copies)

B206150198 B20604
PDR ADOCK 05000316
PDR

JUN 9 1982

IE29