



GULF STATES UTILITIES COMPANY

POST OFFICE BOX 2951 • BEAUMONT, TEXAS 77704

AREA CODE 713 838-6631

June 4, 1982
KRG-12,762
File Nos. G9.5, G9.25.1.1

Mr. John T. Collins, Regional Administrator
U. S. Nuclear Regulatory Commission
Region IV, Office of Inspection and Enforcement
611 Ryan Plaza Drive, Suite 1000

Arlington, Texas 76011

Dear Mr. Collins:

River Bend Station Unit 1
Docket No. 50-458
Interim Report/DR-38


On February 23, 1982, Gulf States Utilities Company (GSU) notified your office of a deficiency potentially reportable under 10CFR50.55(e). The deficiency (DR-38) concerned a difference found in serration patterns of PS-10RS spring nuts supplied to GSU when compared to nuts previously supplied. On June 4, 1982 GSU determined that the potentially reportable deficiency was reportable, and notified your office by telephone. GSU will provide the report required under paragraph 3 of 10CFR50.55(e) within thirty (30) days.

Sincerely,

J. E. Booker
Manager-Engineering & Licensing
River Bend Nuclear Group

JEB
JEB/RJK/kt

cc: Director of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555



1E-27