

DUKE POWER COMPANY

POWER BUILDING

422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28242

WILLIAM O. PARKER, JR.
VICE PRESIDENT
STEAM PRODUCTION

June 9, 1982

TELEPHONE: AREA 704
373-4083

Mr. Richard C. DeYoung, Director
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Attention: Mr. Robert F. Heishman, Acting Chief
Reactor Construction Branch

Re: McGuire Nuclear Station
Docket Nos. 50-369, 50-370

Dear Mr. DeYoung:

Duke Power Company has reviewed Mr. Heishman's letter of May 28, 1982 concerning the inspection conducted by Mr. A. R. Johnson of activities at Wyle Laboratories during the period March 25 - April 1, 1982. None of the information contained in this letter is considered to be proprietary by Duke Power Company.

During our review of this report, several technical errors were noted in the Details Section of the attachment. These errors are as follow:

Section C.2.a - Second sentence should read, "On 3/30/82 at 9:00 a.m., 120 hours into the accident profile (from time 0), at the saturated soak plateau of 228°F, the..."

Section C.2.a - Sixth sentence, parentheses at end of sentence should be "...(228°F plateau)."

Section C.2.b - Second sentence, phrase in middle of sentence should read, "...at the saturated soak plateau of 228°F,..."

Section C.2.c - First paragraph, second sentence, phrase in middle of sentence should read, "...at the saturated soak plateau of 228°F,..."

Section C.2.c - Second paragraph, first sentence, phrase in middle of sentence should read, "...at the saturated soak plateau of 250°F,..."

All of these corrections were discussed with Mr. A. R. Johnson, NRC/Region IV, on June 7, 1982 and he agreed that these changes were correct.

With regard to the identified unresolved item, Duke Power Company described the test results in a letter to Mr. H. R. Denton dated April 9, 1982. This same letter also indicated that additional testing would be conducted to determine the cause of the erratic behavior of several of the modules. The follow-on testing has been completed satisfactorily. A report describing the entire test program will be submitted in August, 1982.

1201

Mr. R. C. DeYoung, Director
June 9, 1982
Page 2

Very truly yours,

William O Parker Jr.
William O. Parker, Jr. *by WAH*

GAC/php

cc: Mr. James P. O'Reilly, Regional Administrator
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Mr. P. R. Bemis
NRC Senior Resident Inspector
McGuire Nuclear Station

Mr. R. A. Birkel
Office of Nuclear Reactor Regulation
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Mr. A. R. Johnson
U. S. Nuclear Regulatory Commission
Region IV
611 Ryan Plaza Drive
Arlington, Texas 76012

Mr. W. S. Farmer
Office of Nuclear Regulatory Research
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555