



**PUBLIC
SERVICE
INDIANA**

S. W. Shields
Senior Vice President
Nuclear Division

June 14, 1982
S82-05
SVP-0006-82

Mr. James G. Keppler,
Regional Administrator
U.S. Nuclear Regulatory Commission
Region III
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Docket Nos.: STN 50-546
STN 50-547
Construction Permit Nos.:
CPPR - 170
CPPR - 171

Marble Hill Nuclear Generating Station - Units 1 and 2

Dear Mr. Keppler:

On March 5, 1982, Mr. T. D. Geib of Public Service Company of Indiana, Inc. (PSI) notified your office of a potentially reportable item as required by 10 CFR 50.55(e). Pullman Construction Industries', Inc. (PCI) shop issued a report under 10 CFR 21 identifying that certain fillet welds had been omitted from heating, ventilating and air conditioning (HVAC) ductwork stiffeners. Some of this ductwork has been delivered to the site by PCI.

Review of this condition by the plant designer, Sargent & Lundy, indicates that some of the ductwork will require the presence of the missing weld to perform adequately. PSI has therefore instructed PCI to complete the welds as originally designed. For ductwork previously delivered to the site the welds will be repaired during the erection process.

This letter is intended to fulfill the requirements of a final report as defined in 10 CFR 50.55(e). If you have any questions on this report, please feel free to contact me.

Sincerely,

S. W. Shields

SWS/TDG/bak

8206170293 820614
PDR ADOCK 05000546
S PDR



PUBLIC
SERVICE
INDIANA

James G. Keppler

-2-

June 14, 1982
S82-05
SVP-0006-82

cc: Director of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, D. C. 20555

J. E. Konklin
J. J. Harrison