

*Southern California Edison Company*

SAN ONOFRE NUCLEAR GENERATING STATION

P.O. BOX 128

SAN CLEMENTE, CALIFORNIA 92672

H. B. RAY  
STATION MANAGER

June 7, 1982

RECEIVED  
NRC

1982 JUN -9 PM 12:35

REGION V  
TELEPHONE  
(714) 492-7700

U.S. Nuclear Regulatory Commission  
Office of Inspection and Enforcement  
Region V  
1450 Maria Lane, Suite 210  
Walnut Creek, California 94596-5368

Attention: Mr. R. H. Engelken, Regional Administrator

Dear Sir:

Subject: Docket No. 50-361  
Licensee Event Report No. 82-014  
San Onofre Nuclear Generating Station, Unit 2

Reference: (a) Letter, H.B. Ray (SCE) to R.H. Engelken (NRC) dated  
May 14, 1982 - Special Report, Inoperable Fire Rated  
Assemblies

In accordance with Technical Specification 6.9.1.12.b, this letter confirms our prompt notification of your office by telephone on June 4, 1982, of a reportable occurrence involving the discovery of additional inoperable fire barrier penetration seals, beyond those addressed in Reference (a), for which inadequate compensatory measures had been established.

On June 4, 1982, a listing of improperly sealed refractory blankets on cable tray penetrations of fire barriers was provided to SCE by the contractor. It was determined that the fire watches that had been established in accordance with the Action Statement associated with Limiting Condition for Operation 3.7.9 for those inoperable fire rated assemblies addressed in Reference (a) did not provide adequate compensatory measures for fire protection in these additional areas.

Area fire detectors were confirmed to be operable and fire watches were posted as necessary. Corrective action to install the mastic coating seals where the refractory blankets butt against the fire barriers was commenced and the additional inoperable fire barrier seals were incorporated into the compensatory fire protection program delineated in the Reference (a) Special Report.

The scheduled update of the Reference (a) Special Report will be issued on June 11, 1982, and will constitute the 14-day follow-up report to this prompt notification as required by Section 6.9.1.12 of the Unit 2 Technical Specifications.

IE22

8206210303 820607  
PDR ADOCK 05000361  
S PDR


Mr. R. H. Engelken

-2-

June 7, 1982

A completed LER form addressing the discovery of these additional inoperable seals will be provided with that update. If there are any questions regarding the above, please contact me.

Sincerely,

A handwritten signature in dark ink, appearing to read 'A.E. Chaffee', with a long, sweeping horizontal stroke extending to the right.

cc: A.E. Chaffee (USNRC Resident Inspector, San Onofre, Unit 2)