



LOUISIANA
POWER & LIGHT

142 DELARONDE STREET
P. O. BOX 6008 • NEW ORLEANS, LOUISIANA 70174 • (504) 366-2345


June 17, 1982

G. D. McLENDON
Senior Vice President

W3K82-0353

Q-3-A35.07.40

Mr. John T. Collins, Regional Administrator, Region IV
U. S. Nuclear Regulatory Commission
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76012



SUBJECT: Waterford SES Unit No. 3
Docket No. 50-382
Significant Construction Deficiency No. 40
"ITE-Gould Starter Coil Failure in Containment Cooling Fans"
Fourth Interim Report

Reference: 1) LP&L Letter W3K82-0320 to NRC dated June 3, 1982
2) Telecon - L. Martin (NRC) to L. Bass (LP&L) on June 16, 1982

Dear Mr. Collins:

In reference (1) LP&L committed to submit a final report on the subject Significant Construction Deficiency on June 15, 1982.

The final review of installation documents is now in process and is expected to be completed by June 30, 1982. A final report will be submitted on or before July 12, 1982.

Very truly yours,

G. D. McLendon

GDMcL/LLB/ncd

- cc: 1) Director
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555
- 2) Director
Office of Management
Information and Program Control
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

ITE-27