

DUKE POWER COMPANY
POWER BUILDING
422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28242

June 23, 1982

WILLIAM O. PARKER, JR.
VICE PRESIDENT
STEAM PRODUCTION

82 JUN 28 8:30
USNRC REGION II
ATLANTA, GEORGIA
TELEPHONE: AREA 702
373-4083

Mr. James P. O'Reilly, Regional Administrator
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Re: McGuire Nuclear Station Unit 1
Docket No. 50-369

Dear Mr. O'Reilly:

Reportable Occurrence Report RO-369/82-37 was to have been submitted by June 18, 1982. This 30 day reportable occurrence (per T.S.6.9.1.13) concerns T.S.3.6.1.8, "Two independent Annulus Ventilation Systems shall be operable"; and T.S.3.9.11, "The Fuel Handling Ventilation Exhaust System shall be operating and discharging through the HEPA filters and charcoal absorbers", which were violated on May 19, 1982. At this time investigation of the incident and preparation of a report are not yet complete. The report will be submitted by June 30, 1982.

Very truly yours,

William O. Parker, Jr.
William O. Parker, Jr.

PBN/jfw

cc: Director
Office of Management and Program Analysis
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Records Center
Institute of Nuclear Power Operations
1820 Water Place
Atlanta, Georgia 30339

Mr. P. R. Bemis
Senior Resident Inspector - NRC
McGuire Nuclear Station

OFFICIAL COPY

IE 22