

DUKE POWER COMPANY

POWER BUILDING

422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28242

WILLIAM O. PARKER, JR.
VICE PRESIDENT
STEAM PRODUCTION

July 1, 1982

TELEPHONE AREA 704
373-4093

Mr. James P. O'Reilly, Regional Administrator
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Re: McGuire Nuclear Station
Unit 2
Docket No. 50-370

Dear Mr. O'Reilly:

In the "Corrective Action" section of Significant Deficiency Report SD 370/81-10 it was stated that modification kits for the Westinghouse SA-1 relays were being ordered and were expected to be installed by July 1, 1982. Due to delays in obtaining the modified relays this work is now expected to be completed by fuel loading.

Very truly yours,

William O. Parker, Jr.
William O. Parker, Jr.

PBN/php

cc: Director
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Mr. P. R. Bemis
Senior Resident Inspector
McGuire Nuclear Station

OFFICIAL COPY

IE 27

8207090213 820701
PDR ADDCK 05000370
S PDR