

Georgia Power Company
333 Piedmont Avenue
Atlanta, Georgia 30308
Telephone 404 526-7025

Mailing Address:
Post Office Box 4545
Atlanta, Georgia 30302

July 9, 1982



W. A. Widner
Vice President and General Manager
Fossil and Hydro Generation

Director of Nuclear Reactor Regulation
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Attention: Mr. Mort Fairtile

NRC DOCKETS 50-321, 50-366
OPERATING LICENSES DPR-57, NPF-5
EDWIN I. HATCH NUCLEAR PLANT UNITS 1, 2
RESPONSE TO FRANKLIN RESEARCH CENTER REQUEST
FOR ADDITIONAL INFORMATION ON INSTALLED TMI
ACTION PLAN ITEMS

Gentlemen:

The following is submitted in response to the NRC letter dated June 7, 1982 which contained a request from Franklin Research for additional information on the correlation between TMI action plan equipment and the specific sections in NUREG-0737. Separate enclosures are provided for Units 1 and 2 listing the appropriate TMI action plan sections and any installed equipment within the scope of each section. These two enclosures list all TMI action plan equipment presently within the scope of I&E Bulletin 79-01B. In the future, any equipment procured to meet the NUREG-0737 requirements which falls within the 79-01B scope will be fully qualified to meet NUREG-0588 requirements.

If there are any questions regarding this response, please contact this office.

Very truly yours,

W.A. Widner

W. A. Widner

CBS/mb

Enclosure

xc: H. C. Nix, Jr.
R. F. Rogers, III
J. P. O'Reilly (NRC-Region II)

A046

8207150458 820709
PDR ADOCK 05000321
PDR

ATTACHMENT 1

HATCH UNIT 1 - TMI ITEMS

NUREG-0737 Section

MPL Number

II.B.3	*
II.D.3	B21-PS-N301A,B,C,D,E,F,G,H,J,K,L
II.D.3	C12-14T
II.E.4.1	*
II.E.4.2	B21-SV-F111
II.E.4.2	B21-SV-F112
II.E.4.2	B21-SV-F113
II.E.4.2	E41-SV-F121
II.E.4.2	E41-SV-F122
II.F.1	D11-RE-N003A,B
II.F.1	D11-RE-N022A,B
II.F.1	H1-16
II.F.1	P33-P001A,B
II.F.1	P48-PT-N020A,B
II.F.1	P48-LT-N021A,B
II.F.1	R11-S039
II.F.1	R11-S040
II.F.1	Panelboard in MC R24-S011
II.F.1	Panelboard in MC R24-S012
II.F.1	T48-E/S-K007A,B
II.F.1	T48-E/S-K008A,B
II.F.1	T48-E/S-K009A,B
II.F.1	T48-E/S-K019A,B
II.F.1	T48-E/S-K020A,B
II.F.1	T48-PT-N003A,B
II.F.1	T48-PT-N008A,B
II.F.1	T48-PT-N009A,B
II.F.1	T48-LT-N010A,B
II.F.1	T48-PT-N020A,B
II.F.1	T48-LT-N021A,B
II.F.1	T48-PT-N023A,B
II.K.3.13	*
II.K.3.15	*
II.K.3.19	*
II.K.3.21	*
II.K.3.27	*

*No equipment within I&E Bulletin 79-01B scope.

ATTACHMENT 2

HATCH UNIT 2 - TMI ITEMS

NUREG-0737 Section

MPL Number

II.B.3	*
II.D.3	2B21-PSN301A,B,C,D,E,F,G,H,K,L,M
II.E.4.1	*
II.E.4.2	2B21-SV-F111
II.E.4.2	2B21-SV-F112
II.E.4.2	2B21-SV-F113
II.E.4.2	2E41-SV-F121
II.F.1	2D11-RE-N003A,B
II.F.1	2P33-P001A,B
II.F.1	2T48-PT-N003A,B
II.F.1	2T48-LT-N010A
II.F.1	2T48-PT-N020A,B
II.F.1	2T48-PT-N021A
II.F.1	2T48-LT-N021A
II.F.1	2T48-PT-N023A
II.F.1	2D11-RE-N022B
II.F.1	J03
II.F.1	J04
II.F.1.3	2D11-RE-N022A
II.F.1.4	2T48-E/S-K009A,B
II.F.1.4	2T48-E/S-K019A,B
II.F.1.5	2T48-E/S-K007A,B
II.F.1.5	2T48-E/S-K020A,B
II.F.1.5	2T48-LT-N010A
II.F.1.5	2T48-LT-N021A
II.K.3.13	*
II.K.3.15	*
II.K.3.19	*
II.K.3.21	*
II.K.3.27	*

*No equipment within I&E Bulletin 79-01B scope.