



GULF STATES UTILITIES COMPANY

POST OFFICE BOX 2951 • BEAUMONT, TEXAS 77704

AREA CODE 713 838-6631

July 9, 1982


RBG-12,987

File Nos. G9.5, G9.25.1.1

Mr. John T. Collins, Regional Administrator
U. S. Nuclear Regulatory Commission
Region IV, Office of Inspection and Enforcement
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76011

Dear Mr. Collins:

River Bend Station Unit 1
Docket No. 50-458
Interim Report/DR-31



On December 11, 1981, Gulf States Utilities Company (GSU) notified the Nuclear Regulatory Commission's Region IV Office of a condition potentially reportable under 10CFR50.55(e) concerning loose mounting screws or fasteners used to assemble or mount the position switch assembly on valve motor operators supplied by Limitorque (DR-31). GSU has not completed its investigation at this time. An interim or final status report will be submitted by August 12, 1982.

Sincerely,

J. E. Bocker
Manager-Engineering & Licensing
River Bend Nuclear Group

JEB/RJK/kt

cc: Director of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555