



LOUISIANA
POWER & LIGHT


142 DELARONDE STREET
P. O. BOX 6008 • NEW ORLEANS, LOUISIANA 70174 • (504) 366-2345

July 6, 1982

G. D. McLENDON
Senior Vice President

W3K-82-0390
Q-3-A35.07.41

Mr. John T. Collins, Regional Administrator, Region IV
U. S. Nuclear Regulatory Commission
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76012



Subject: Waterford SES Unit No. 3
Docket No. 50-382
Significant Construction Deficiency No. 41
"UNAPPROVED WELDING"

Reference: 1) LP&L Letter W3K-82-0320

Dear Mr. Collins:

Due to extensive rework required to complete the corrective
action, the final report will be submitted on August 16, 1982.

If you have any questions, please contact me.

Very truly yours,

G. D. McLendon

- cc: 1) Director
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555
- 2) Director
Office of Management
Information and Program Control
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

IE-27