



**LOUISIANA
POWER & LIGHT**


142 DELARONDE STREET
P. O. BOX 6008 • NEW ORLEANS, LOUISIANA 70174 • (504) 366-2345

July 6, 1982

G. D. McLENDON
Senior Vice President

W3K-82-0392
Q-3-A35.07.47

Mr. John T. Collins, Regional Administrator, Region IV
U. S. Nuclear Regulatory Commission
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76012



Subject: Waterford SES Unit No. 3
Docket No. 50-382
Significant Construction Deficiency No. 47
"G.E. AKR 30/50 Circuit Breakers Closing Spring Screw"

Reference: LP&L Letter W3K-82-0146

Dear Mr. Collins:

In referenced letter, a request for an extension for submittal of a final report was issued as replacement parts needed for completion of corrective action had not been received.

Parts have subsequently been received and placed on "hold" and awaiting proper documentation from supplier.

Corrective action should be completed by July 30, 1982, at which time a final report will be submitted.

If any questions exist, please contact me.

Very truly yours,

G. D. McLendon

cc: 1) Director
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

2) Director
Office of Management
Information and Program Control
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

8207190273 820706
PDR ADOCK 05000382
S PDR

IE-27