

*Southern California Edison Company*

SAN ONOFRE NUCLEAR GENERATING STATION

P.O. BOX 128

SAN CLEMENTE, CALIFORNIA 92672

H. B. RAY  
STATION MANAGER

July 9, 1982

TELEPHONE  
(714) 492-7700

U. S. Nuclear Regulatory Commission  
Office of Inspection and Enforcement  
Region V  
1450 Maria Lane, Suite 210  
Walnut Creek, California 94596-5368

Attention: Mr. R. H. Engelken, Regional Administrator

Dear Sir:

Subject: Docket No. 50-361  
Additional Information  
Licensee Event Report Nos. 82-024 and 82-025  
San Onofre Nuclear Generating Station, Unit 2

Reference: Letter, H. B. Ray (SCE) to R. H. Engelken (NRC),  
14-Day Follow-up Reports LER 82-024 and 82-025,  
Dated June 23, 1982

On June 23, 1982 the referenced correspondence transmitted the 14-Day Follow-up Reports and LER's 82-024 and 82-025 concerning two inadvertent violations of the Technical Specifications 3.0.4 and 3.7.1.2 Action b. In that letter, we stated that an investigation to determine the cause of the oversight in failing to recognize in a timely manner the full impact of the Work Order on valve 2HV4713 and AFW System operability was continuing. We also stated that any corrective actions resulting from this investigation would be identified by July 9, 1982.

We have completed our investigation and this submittal provides that information.

The oversight resulted from inadequate review of the Maintenance Work Order (W.O.) by the SRO. The W.O. did not provide sufficient information to serve as a valid basis for the SRO's decision not to declare the AFW train associated with Pump P-141 inoperable. He did not recognize this and hence the error.

8207190476 820709  
PDR ADOCK 05000361  
S PDR


JE-29

July 9, 1982

We had recognized the need for a Program revision before the incident and had initiated action to write and issue new procedure S023-0-26, "Equipment Deficiencies". This procedure describes and clarifies the Operations Department implementation of its responsibilities associated with Maintenance activity. When issued, this new procedure will result in clearer documentation on Work Orders of problems to be corrected, verification of these descriptions by knowledgeable individuals, and more complete reviews for Technical Specifications LCO impact. The new procedure will be issued by August 27, 1982.

If you have any questions regarding the above, please contact me.

Sincerely,

A handwritten signature in cursive script, appearing to read 'R. H. Engelken', written in dark ink.

cc: Mr. A. E. Chaffee (USNRC Resident Inspector, San Onofre Unit 2)

U. S. Nuclear Regulatory Commission  
Office of Inspection and Enforcement

U. S. Nuclear Regulatory Commission  
Office of Management Information & Program Control

Institute of Nuclear Power Operations

Mr. R. H. Engelken

-3-

July 9, 1982

bcc: OSRC Members (10)

R. Dietch  
J. G. Haynes  
H. B. Ray  
K. P. Baskin/M. O. Medford  
J. M. Curran/D. B. Schone  
D. E. Nunn/H. L. Richter  
W. C. Moody  
W. W. Stromm (NSG)  
C. R. Kocher/J. A. Beoletto  
E. N. Cramer  
D. R. Piggot, Esq. (Orrick, Herrington & Sutcliffe)  
P. A. Croy  
J. S. Iyer  
H. E. Morgan  
J. R. Tate  
P. H. Penseyres (STA)  
B. Katz  
H. Mathis  
Engineering Files  
CDM Files