

BALTIMORE GAS AND ELECTRIC COMPANY

D. UNDATED ORIGINAL

P.O. BOX 1475

Certified By *mlt*

BALTIMORE, MARYLAND 21203

HUR E. LUNDWALL, JR.

VICE PRESIDENT
Supply

1 July, 1982

Mr. Ronald C. Haynes, Director
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
Region I
631 Park Avenue
King of Prussia, PA. 19406

Docket No. 50-318
License No. DPR-69

SUBJECT: LER 82-30, Unit 2

Dear Mr. Haynes

This letter is to confirm our verbal notification of your Mr. Ralph Architzel of the discovery that a hole had been drilled between the Switchgear Room and the Main Steam Penetration Room during power operation.

At 1645 on 6-30-82 with Unit 2 in Mode 1 it was discovered that a 4 inch hole had been drilled between the Main Steam Penetration Room and the 27th Switchgear Room. The existence of this breach in the Main Steam Penetration Room wall contradicts Section 10A.1.11 of the FSAR which states that other areas of the Auxiliary Building will not be affected by a high energy line break in the Main Steam Penetration Room. This is considered reportable in accordance with Technical Specification 6.9.1.8.f. No limiting condition for operation was affected. This hole was sealed at 1700, thus terminating the event.

A complete description of the events leading to this discovery and further corrective actions will be addressed in the follow-up report.

Very truly yours,

LBRussell

L. B. Russell

Plant Superintendent

LBR:fld

cc: J. A. Tiernan
Director, Office of Management
Information & Program Control
G. S. Pavis

R. M. Douglass
R. E. Architzel
L. B. Russell

8207220549 820701
PDR ADOCK 05000318
S PDR

IE29