

No. 3-82-11/3L

This LER concerns the failure of a drywell pressure transmitter. Applicable Tech Spec is 4.2.F.

LICENSEE EVENT REPORT

CONTROL BLOCK: 1 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 P A P B S 3 2 0 0 - 0 0 0 0 0 0 0 0 3 4 1 1 1 4 5
 7 8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58

CON'T
 01 REPORT SOURCE L 6 0 5 0 - 0 2 7 8 7 0 6 2 0 8 2 8 0 7 1 1 3 8 2 9
 7 8 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10
 02 While restoring power supply to service following a loss of power
 03 test the fuse on the positive leg to the transmitter circuit board
 04 blew causing a downscale failure of the drywell 0-70 PSIG pressure
 05 recorder. The redundant 0-70 PSIG pressure recorder was verified
 06 operable. Applicable Tech Spec is 4.2.F.
 07
 08

09 SYSTEM CODE I D 11 CAUSE CODE E 12 CAUSE SUBCODE A 13 COMPONENT CODE C K T B R K 14 COMP SUBCODE X 15 VALVE SUBCODE Z 16
 7 8 9 10 11 12 13 18 19 20

17 LER/RO REPORT NUMBER 8 2 21 22 0 1 1 23 24 26 0 3 25 26 27 0 3 28 29 L 30 31 0 32
 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48

ACTION TAKEN A 18 FUTURE ACTION F 19 EFFECT ON PLANT Z 20 SHUTDOWN METHOD Z 21 HOURS 0 0 0 0 22 ATTACHMENT SUBMITTED N 23 NPRD-4 FORM SUB Y 24 PRIME COMP SUPPLIER A 25 COMPONENT MANUFACTURER X 9 9 9 26

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27
 10 The cause of the blown 0.3 AMP fuse was attributable to an
 11 intentional ground installed on the positive side of the transmitter
 12 The fuse was replaced and the recorder immediately returned to
 13 service. A modification is in progress to change the transmitter
 14 circuit board to eliminate the positive ground.
 15

16 FACILITY STATUS E 28 % POWER 1 0 0 29 OTHER STATUS U/2 Refuel 30 METHOD OF DISCOVERY A 31 DISCOVERY DESCRIPTION Operator Observation 32
 7 8 9 10 11 12 13 44 45 46 80

16 ACTIVITY CONTENT RELEASED OF RELEASE 2 33 34 35 AMOUNT OF ACTIVITY N/A 36 LOCATION OF RELEASE N/A 37
 7 8 9 10 11 12 13 44 45 46 80

17 PERSONNEL EXPOSURES NUMBER 0 0 0 37 TYPE Z 38 DESCRIPTION N/A 39
 7 8 9 10 11 12 13 44 45 46 80

18 PERSONNEL INJURIES NUMBER 0 0 0 40 DESCRIPTION N/A 41
 7 8 9 10 11 12 13 44 45 46 80

19 LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION N/A 43
 7 8 9 10 11 12 13 44 45 46 80

20 PUBLICITY ISSUED N 44 DESCRIPTION N/A 45
 7 8 9 10 11 12 13 44 45 46 80

NAME OF PREPARER M. J. Cooney
 PHONE (215) 841-5020