




LOUISIANA
POWER & LIGHT

142 DELARONDE STREET
P O BOX 6008 • NEW ORLEANS, LOUISIANA 70174 • (504) 366-2345



July 15, 1982

G. D. McLENDON
Senior Vice President

W3K 82-0419
Q-3-A35.07.29

Mr. John T. Collins, Regional Administrator, Region IV
U. S. Nuclear Regulatory Commission
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76012

Subject: Waterford SES Unit No. 3
Docket No. 50-382
Significant Construction Deficiency No. 29
"Inadequate Clearance Between Process Piping Systems
and Box-Type Pipe Supports/Restraints"
Second Interim Report

Reference: 1) LP&L Letter W3K 81-0257 to NRC dated July 14, 1981
2) Telecon - R. G. Bennett (LP&L) to L. Martin (NRC) on July 12, 1982

Dear Mr. Collins:

LP&L committed to submitting the final report on this Significant Construction Deficiency on June 30, 1982. We are unable to meet the scheduled date.

Nonconformance Report W3-2644 is the controlling document for tracking the work activity involved in the corrective action. Upon completion of work activity, documentation review, and closure of NCR W3-2644, the final report on Significant Construction Deficiency 29 will be submitted on or before October 15, 1982.

If you have any questions, please call me.

Very truly yours,

8207230311 820715
PDR ADOCK 05000382
S PDR

GDMcL/LLB/grf

cc: 1) Director
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

2) Director
Office of Management
Information and Program Control
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

TE 27