

# DUKE POWER COMPANY

POWER BUILDING

422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28242

WILLIAM O. PARKER, JR.  
VICE PRESIDENT  
STEAM PRODUCTION

July 7, 1982

TELEPHONE: AREA 704  
373-4083  
JUL 20 1982  
A 8:51  
NRC REGION 1  
INTRA REGION


Mr. James P. O'Reilly, Regional Administrator  
U. S. Nuclear Regulatory Commission  
Region II  
101 Marietta Street, Suite 3100  
Atlanta, Georgia 30303

Re: Oconee Nuclear Station  
Docket No. 50-269

Dear Mr. O'Reilly:

On June 23, 1982, your office was informed that both trains of the Reactor Building Spray system were inoperable. This constitutes an operation subject to a limiting condition for operation which was less conservative than the least conservative aspect of the limiting condition for operation established in the Technical Specifications. Reportable Occurrence Report RO-269/82-12, providing details of this incident was to have been submitted to you by July 7, 1982, pursuant to Technical Specification 6.6.2.1.a(2). However, the investigation of this incident and preparation of a report are incomplete at this time. It is expected that the investigation and report will be completed, reviewed, and submitted to you by July 21, 1982.

Very truly yours,



William O. Parker, Jr.

JFK/php

cc: Document Control Desk  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

Mr. W. T. Orders  
NRC Resident Inspector  
Oconee Nuclear Station

Records Center  
Institute of Nuclear Power Operations  
1820 Water Place  
Atlanta, Georgia 30339

8207230667 820707  
PDR ADOCK 05000269  
S PDR

OFFICIAL COPY

IE 22