

NSP

NORTHERN STATES POWER COMPANY

Monticello Nuclear Generating Plant
Monticello, Minnesota 55902

September 23, 1975

Mr. J. G. Keppler, Director
Region III
Office of Inspection and Enforcement
United States Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Dear Mr. Keppler:

MONTICELLO NUCLEAR GENERATING PLANT
Docket No. 50-263 License No. DPR-22

On September 23, 1975, local leak rate testing of the Standby Liquid Control outboard isolation valve, XF-6, indicated that the leakage exceeded the Technical Specification acceptance criteria. Further investigation of this occurrence is continuing.

Yours very truly,

C. E. Larson
C. E. Larson
Plant Manager

CEL/jmm

cc: R. S. Boyd
G. Charnoff
Minnesota Pollution Control Agency
Attn: J. W. Fernan
File

Copies sent by teletypewriter to Keppler and Boyd

Rec'd 240 9/23/75

9102120610 750923
CF ADDCK 05000263
CF