

Duke Power Company
McGuire Nuclear Generation Department
12700 Rogers Ferry Road (MG01A)
Huntersville, NC 28078-8985

T. C. McMEEKIN
Vice President
(704)875-4800
(704)875-4809 FAX



DUKE POWER

May 3, 1993

U.S. Nuclear Regulatory Commission
Document Control Desk
Washington, D.C. 20555

Subject: McGuire Nuclear Station Unit 1 & 2
Docket No. 50-369
Licensee Event Report 369/93-03
Problem Investigation Process No.: 0-M93-0198

Gentlemen:

Pursuant to 10 CFR 50.73 Sections (a) (1) and (d), attached is Licensee Event Report 369/93-03 concerning The Past Inoperability Of Train B Of The Control Room Ventilation System Due To A Possible Fabrication/ Installation Deficiency. This report is being submitted in accordance with 10 CFR 50.73 (a) (2) (i). This event is considered to be of no significance with respect to the health and safety of the public.

Very truly yours,

T.C. McMeekin

TLP/bcb

Attachment

xc: Mr. S.D. Ebnetter
Administrator, Region II
U.S. Nuclear Regulatory Commission
101 Marietta St., NW, Suite 2900
Atlanta, GA 30323

INPO Records Center
Suite 1500
1100 Circle 75 Parkway
Atlanta, GA 30339

Mr. Victor Nerses
U.S. Nuclear Regulatory Commission
Office of Nuclear Reactor Regulation
Washington, D.C. 20555

Mr. P.K. Van Doorn
NRC Resident Inspector
McGuire Nuclear Station

9305120048 930503
PDR ADDCK 05000369
S PDR

JE221