

COVER SHEET

1RE04 INSERVICE INSPECTION SUMMARY REPORT  
FOR REPAIRS & REPLACEMENTS  
(CLASS 1 AND 2)

ADDENDUM - 1

AT THE

SOUTH TEXAS PROJECT ELECTRIC GENERATING STATION UNIT 1  
P. O. Box 289  
Wadsworth, Texas 77483

USNRC DOCKET NO.: 50-498

OPERATING LICENSE NO.: NPF-76

COMMERCIAL OPERATION DATE: August 25, 1988

Prepared by: *A.P. Pathak* 5-13-93  
A. P. Pathak, Consulting Engineer - Codes & Standards

Reviewed by: *S. Timmaraju* 5-13-93  
S. Timmaraju, Sr. Consulting Engineer - Codes & Standards

Approved by: *M. Pacy*  
M. Pacy, Manager - Design Engineering Department

MBS/149.AP

9305190305 930514  
PDR ADDCK 0500049B  
Q PDR

SOUTH TEXAS PROJECT UNIT - 1  
ASME CODE SECTION - XI  
1RE04 INSERVICE INSPECTION SUMMARY REPORT FOR  
REPAIRS AND REPLACEMENTS  
(CLASS 1 AND 2)  
ADDENDUM - 1

R OR R NO.	SR NO.	PROJ. ID OF ITEM (TPNS NO.)	MFG., SN AND NB (IF ANY) OF COMP.	ITEM/COMP DESCRIPTION	R OR R DESCRIPTION	ANH	COMP. DATE
1-90-367	MS-128160	N/A	WESTINGHOUSE SN: TO 4862	MANWAY COVER (SPARE) FOR STEAM GENERATOR	REPAIRED BY WELDING	B. RUSSELL TX-826	4-28-93
1-90-071	CV-105420	2R171TCV0236B	ANDERSON- GREENWOOD SN: A3830	VALVE	REPLACED VALVE	B. RUSSELL TX-826	4-28-93
1-92-030	CS-118286 (EP03)	CS SYSTEM	HL&P SN: N/A	PANCAKE BLINDS	FABRICATED PANCAKE BLINDS	B. RUSSELL TX-826	4-30-93
1-92-031	CS-118286 (EP02)	LINES: CS-1105 CS-1106 CS-1115	HL&P SN: N/A	PANCAKE BLINDS AND FLANGES	INSTALLED PANCAKE BLINDS AND FLANGES	B. RUSSELL TX-826	4-30-93
1-92-032	CS-118244 (EP01)	LINES: CS-1205 CS-1206 CS-1215	HL&P SN: N/A	PANCAKE BLINDS AND FLANGES	INSTALLED PANCAKE BLINDS AND FLANGES	B. RUSSELL TX-826	4-30-93
1-92-033	CS-118245 (EP01)	LINES: CS-1305 CS-1306 CS-1315	HL&P SN: N/A	PANCAKE BLINDS AND FLANGES	INSTALLED PANCAKE BLINDS AND FLANGES	B. RUSSELL TX-826	4-30-93
1-92-042	FW-134660 (EP01)	SPOOLS: AF-1117-D AF-1117-E AF-1117-F AF-1119-D AF-1119-E AF-1119-F AF-1121-D AF-1121-E AF-1121-F AF-1123-D AF-1123-E AF-1123-F	HL&P SN: N/A	PIPING SPOOLS	REPLACED CARBON STEEL SPOOLS WITH STAINLESS STEEL SPOOLS	B. RUSSELL TX-826	5-3-93
1-92-043	FW-134660 (EP02)	VARIOUS	NPSI AND HL&P SN: N/A	COMPONENT SUPPORTS	REWORKED VARIOUS SUPPORTS	B. RUSSELL TX-826	5-4-93

SOUTH TEXAS PROJECT UNIT - I  
ASME CODE SECTION - XI  
1REF04 INSERVICE INSPECTION SUMMARY REPORT FOR  
REPAIRS AND REPLACEMENTS  
(CLASS 1 AND 2)  
ADDENDUM - 1

R OR R NO.	SR NO.	PROJ. ID OF ITEM (TPNS NO.)	MFG., SN AND NB (IF ANY) OF COMP.	ITEM/COMP DESCRIPTION	R OR R DESCRIPTION	ANII	COMP. DATE
1-92-044	RC-111536 (EP01,EP02)	1R141TRC0132	EDWARD VALVES SN: 39AEN	VALVE	REPLACED VALVE	B. RUSSELL TX-826	4-29-93
1-92-045	RC-1115664 (EP01,EP02)	LINES: RC-1050 RC-1051	HL&P SN: N/A	RC SYSTEM	REWORKED PIPING AND A SUPPORT	B. RUSSELL TX-826	4-30-93
1-92-046	RC-111539 (EP02,EP03)	LINE: RC-1003 VALVES: RC-0503 RC-0502 SUPPORT: RC1501-HI 5001	PIPING & SUPPORT HL&P SN: N/A VALVES EDWARD VALVES SN: 22A/B, 23A/B TARGET ROCK SN: 1,2,3,4	RC SYSTEM, VALVES AND SUPPORT	INSTALLED A LARGER RCS VENT PATH, NEW VALVES, AND A SUPPORT	B. RUSSELL TX-826	4-29-93
1-92-068	MT-146578	AIMTFV7900A AIMTFV7901A AIMTFV7902A AIMTFV7903A		VALVES	REORIENTED VALVES	B. RUSSELL TX-826	4-28-93
1-92-174	SI-109082	2N121TS10104D	BW/P SN: 881-H-0027	VALVE	REPLACED VALVE	B. RUSSELL TX-826	4-28-93
1-92-237	SI-189804	SPOOL: AF-1019-K	SOUTHWEST FAB SN: 37362	PIPE SPOOL	REPLACED ELBOW	B. RUSSELL TX-826	4-29-93
1-92-244	SI-111850	SPOOL: SI-1301-M SUPPORTS: SI-1301-RR0010 SI-1301-RR0009	SOUTHWEST FAB SN: 15529 NPSI 3006-208F-34-29 3006-208F-34-73	PIPE SPOOL, COMPONENT SUPPORTS	REPAIRED WELD IN SPOOL, REPLACED STRUT ON SUPPORTS	B. RUSSELL TX-826	4-30-93
1-92-261	CV-155734	SI-1206-RR76	NPSI SN: N/A	COMPONENT SUPPORT	REPLACED CLAMP	B. RUSSELL TX-826	4-28-93
1-92-278	MT-146578	AIMTFV7900A	TARGET ROCK SN: 1	VALVE	REPLACED DISC	B. RUSSELL TX-826	4-28-93
1-92-284	AF-111653	2S141TAF0281	ANCHOR DARLING SN: EB 272-10-1	VALVE	REPLACED VALVE	B. RUSSELL TX-826	4-28-93