



GPU Nuclear Corporation
Post Office Box 388
Route 9 South
Forked River, New Jersey 08731-0388
609 971-4000
Writer's Direct Dial Number:

May 11, 1993
C321-93-2146

U. S. Nuclear Regulatory Commission
Att: Document Control Desk
Washington, DC 20555


Dear Sir:

Subject: Oyster Creek Nuclear Generating Station
Docket No. 50-219
Inservice Inspection Data Reports

In accordance with 10 CFR 50.55a(g) and ASME XI Section IWA-6220, 1986 edition with no addenda, GPU Nuclear is forwarding the requisite reports resulting from Inservice Inspection activities conducted during our recently concluded 14R refueling outage. Please note that 14R was the first refueling outage which was scheduled during the third ISI ten year interval.

Attached are the Owner's Data Report for Inservice Inspections, NIS-1, and the Owner's Report for Repairs or Replacements, NIS-2. These reports describe the inspection and repair activities which took place during 14R on pressure retaining weld boundaries.

If any further information is required, please contact Mr. John Rogers of my staff at 609.971.4893.



John J. Barton
Vice President and Director
Oyster Creek

Attachment
JJB/JJR

cc: Administrator, Region I
Senior Resident Inspector
Oyster Creek NRC Project Manager

9305190348 930511
PDR ADOCK 05000219
Q PDR

1047