

Duke Power Company
McGuire Nuclear Generation Department
12700 Hagers Ferry Road (MG01A)
Huntersville, NC 28078-8985

T. C. McMEEKIN
Vice President
(704)875-4800
(704)875-4809 FAX



DUKE POWER

September 5, 1993

Document Control Desk
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Subject: McGuire Nuclear Station, Unit 2
Docket No: 50-370

Dear Sir:


The attached McGuire Unit 2 Steam Leak Investigation and Report describes investigation and actions that were taken and are planned as a result of the steam leak through Unit 2 "A" steam generator secondary side drain line.

The report is the product of two investigations:

- A. A comprehensive review of the actions prior to, during, and in recovery from the event has been conducted under the leadership of E. M. Geddie, Station Manager. Corrective actions were identified and included in the Report.
- B. An independent examination was conducted by a Significant Event Inspection Team (SEIT) under the leadership of W. M. Sample, Safety Assurance Manager, from our Nuclear Services Department.

The resulting recommendations have been reviewed and appropriate actions taken or planned as described in the Report.

I look forward to hearing the results of the NRC Augmented Inspection Team.


T. C. McMeekin

13-1-100
9309140136 930905
PDR ADOCK 05000370
S PDR

AD17/1

McGuire Nuclear Station, Unit 2
Docket No: 50-370
Page 2

xc: Mr. S.D. Ebner
Administrator, Region II
U.S. Nuclear Regulatory Commission
101 Marietta St., NW, Suite 2900
Atlanta, Ga. 30323

Mr. Victor Nerses
U.S. Nuclear Regulatory Commission
Office of Nuclear Reactor Regulation
Washington, D.C. 20555

Mr. G.F. Maxwell
NRC Resident Inspector
McGuire Nuclear Station
U. S. Nuclear Regulatory Commission