

0

NSP

5 50-2825

NORTHERN STATES POWER COMPANY

MINNEAPOLIS, MINNESOTA 55401

November 1, 1978

Mr J G Keppler
Office of Inspection & Enforcement
U S Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137

Dear Mr Keppler:

PRAIRIE ISLAND NUCLEAR GENERATING PLANT
Docket No. 50-282 License No. DPR-42

Opening Make in ABSVZ Boundary
Not Under Administrative Control

The Licensee Event Report for this occurrence is reproduced on the back of this letter. Enclosed are three copies.

This event is reported in compliance with Technical Specification 6.7.B.2.(c) since it represents an inadequacy in the implementation of administrative controls.

Yours very truly,

DM Mayer for
L O Mayer, PE
Manager of Nuclear Support Services

LOM/DM21/deh

cc: Director, IE, USNRC (30)
-Director, MIPC, USNRC (3)
MPCA
Attn: J W Ferman

-over-

781107 0247 S

1002
5/1
HOLD TO
HOLD