



**Commonwealth Edison**

Dresden Nuclear Power Station  
R.R. #1  
Morris, Illinois 60450  
Telephone 815/942-2920

June 25, 1982

DJS Ltr. #82-722

James G. Keppler, Regional Director  
Directorate of Regulatory Operations - Region III  
U.S. Nuclear Regulatory Commission  
799 Roosevelt Road  
Glen Ellyn, IL 60137

Updated Reportable Occurrence Report #81-21/03X-1, Docket #050-249 is being submitted to your office in accordance with Dresden Nuclear Power Station Technical Specification 6.6.B.2 (d), abnormal degradation of systems other than those specified in item B.1.e above designed to contain radioactive material resulting from the fission process. This updated report specifies the cause and mode of repair to the outlet piping on the tube side of 3A-1203A regenerative heat exchanger. Also included is a correction regarding location of the problem area.

D. J. Scott  
Station Superintendent  
Dresden Nuclear Power Station

DJS/nh

Enclosure

cc/ Director of Inspection & Enforcement  
Director of Management Information & Program Control  
U.S. NRC, Document Management Branch  
File/NRC

JUL 19 1982

8207260284 820625  
PDR ADOCK 05000249  
S PDR

IE22



Commonwealth Edison

## DEVIATION REPORT

UPDATED REPORT  
PREVIOUS REPORT DATED 9/28/81DVR NO. 12 - 3 - 81 - 45  
STA UNIT YEAR NO.PART 1 TITLE OF DEVIATION Leak in Piping 3A Rx Water  
Cleanup Regen. Hx Piping OCCURRED 9/1/81 1100  
DATE TIMESYSTEM AFFECTED 1200 Rx Water Cleanup PLANT STATUS AT TIME OF EVENT  
MODE Run, PWR(MWT) 2000, LOAD(MWE) 602 TESTING  
YES NODESCRIPTION OF EVENT An inspection of the 3A-1203A regenerative heat exchanger disclosed  
a leak on the outlet from the heat exchanger (line 3-1204B-6"-A)10 CFR50.72 NRC RED PHONE  
NOTIFICATION MADE YES NOEQUIPMENT FAILURE 15351  
YES NO WORK REQUEST NO. RESPONSIBLE SUPERVISOR Michael Wright DATE 9/2/81PART 2 OPERATING ENGINEER'S COMMENTS All leakage was contained within the Rx building floor  
drain system. The indications are in piping that is outside of the primary containment  
boundary.☐ EVENT OF PUBLIC INTEREST☐ TECH. SPEC. VIOLATION☐ NON REPORTABLE OCCURRENCE☐ 14 DAY REPORTABLE/T.S.☒ 30 DAY REPORTABLE/T.S. 6.6.B.2.d☐ ANNUAL/SPECL REPORT REQ'D

A.I.R. # N/A

L.E.R. # 81-21/03X-1

☐ 24-HOUR NRC NOTIFICATION REQ'DTELEPH N/A  
REGION III DATE TIMETELEGM/TELECOPY N/A  
REGION III DATE TIME☐ CECO CORPORATE NOTIFICATION MADE  
IF ABOVE NOTIFICATION IS PER 10CFR21☐ 5-DAY WRITTEN REPORT REQ'D PER 10CFR21TELEPH F. Palmer 9/2/81 1104  
CECO CORPORATE OFFICER DATE TIMEPRELIMINARY REPORT  
COMPLETED AND REVIEWEDMichael Wright  
OPERATING ENGINEER

9/2/81

INVESTIGATED REPORT & RESOLUTION  
ACCEPTED BY STATION REVIEWJ. A. Cusla  
7-13-82  
DP  
STATION SUPERINTENDENTMichael Wright  
7-13-82  
2/13/82  
DATERESOLUTION APPROVED AND  
AUTHORIZED FOR DISTRIBUTION