

# LICENSEE EVENT REPORT

CONTROL BLOCK: 1 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 N J S G S 2 2 0 0 - 0 0 0 0 0 0 0 0 3 4 1 1 1 1 4 5  
7 8 9 14 15 25 26 30 57 CAT 58

CON'T  
0 1 REPORT SOURCE 1 6 0 5 0 0 0 3 1 1 7 0 6 1 7 8 2 8 0 7 0 7 8 2 9  
7 8 60 61 68 69 74 75 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)  
0 2 On June 17 and 18, 1982, service water flows to No. 21, 22 and 23 Containment Fan Coil  
0 3 Units were observed to be less than the amount required by the Technical Specifications.  
0 4 The CFCU's were declared inoperable, and Action Statements 3.6.2.3a and 3.6.2.3b were  
0 5 entered. The occurrences involved a loss of redundancy in safety systems designed to  
0 6 cool containment after a design basis accident; and constituted operation in a degraded  
0 7 mode in accordance with Technical Specification 6.9.1.9.b.

0 8 9  
SYSTEM CODE S B (11) CAUSE CODE C (12) CAUSE SUBCODE Z (13) COMPONENT CODE H T E X C H (14) COMP. SUBCODE C (15) VALVE SUBCODE Z (16)  
7 8 9 10 11 12 13 18 19 20  
LER NO. REPORT NUMBER (17) EVENT YEAR 8 2 (21) 22 SEQUENTIAL REPORT NO. 0 5 0 (24) 26 OCCURRENCE CODE 0 3 (28) 29 REPORT TYPE L (30) REVISION NO. 0 (32)  
ACTION TAKEN B (18) FUTURE ACTION G (19) EFFECT ON PLANT Z (20) SHUTDOWN METHOD Z (21) HOURS 0 0 0 0 (22) 40 ATTACHMENT SUBMITTED Y (23) 41 NRPD-4 FORM SUB. N (24) 42 PRIME COMP. SUPPLIER A (25) 43 COMPONENT MANUFACTURER W 1 2 0 (26) 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)  
1 0 The low flow to the CFCU's was caused by oysters plugging the SW57 valves. The oysters  
1 1 were removed by cycling or disassembly of the valves. The CFCU's were returned to  
1 2 service, and the action statements were terminated. Development of a revised  
1 3 chlorination program to eliminate the oysters from the Service Water Systems is in  
1 4 progress.

1 5 1 6 1 7 1 8 1 9 2 0  
FACILITY STATUS E (28) % POWER 1 0 0 (29) OTHER STATUS NA (30) METHOD OF DISCOVERY B (31) DISCOVERY DESCRIPTION Surveillance Testing (32)  
7 8 9 10 12 13 44 45 46 80  
ACTIVITY CONTENT RELEASED OF RELEASE Z (33) Z (34) NA (35) AMOUNT OF ACTIVITY LOCATION OF RELEASE NA (36)  
7 8 9 10 11 44 45 80  
PERSONNEL EXPOSURES NUMBER 0 0 0 (37) TYPE Z (38) DESCRIPTION NA (39)  
7 8 9 11 12 13 80  
PERSONNEL INJURIES NUMBER 0 0 0 (40) DESCRIPTION NA (41)  
7 8 9 11 12 80  
LOSS OF OR DAMAGE TO FACILITY TYPE Z (42) DESCRIPTION NA (43)  
7 8 9 10 80  
PUBLICITY ISSUED N (44) DESCRIPTION NA (45)  
7 8 9 10 80  
8207270076 820707  
PDR ADOCK 05000311  
S PDR