

CONTROL BLOCK:

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'T

REPORT  
SOURCE

REPORT SOURCE L 6 0 5 0 0 0 2 7 2 7 0 6 2 3 8 2 8 0 7 2 1 8 2 9

60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

08 03

SYSTEM CODE S G 11		CAUSE CODE X 12		CAUSE SUBCODE Z 13		COMPONENT CODE C K T B R K 14				COMP. SUBCODE F 15		VALVE SUBCODE Z 16					
EVENT YEAR 8 2 22		SEQUENTIAL REPORT NO. 0 4 4 24		OCCURRENCE CODE 0 3 28		REPORT TYPE L 30		REVISION NO. 0 32									
ACTION TAKEN X 18		FUTURE ACTION Z 19		EFFECT ON PLANT Z 20		SHUTDOWN METHOD Z 21		HOURS 0 0 0 0 22		ATTACHMENT SUBMITTED Y 23		NPRD-4 FORM SUB. N 24		PRIME COMP. SUPPLIER A 25		COMPONENT MANUFACTURER I 2 0 3 26	

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 The vital ventilation bus was re-energized, and the fan restored to an operable  
1 1 status at 0307 hours, June 23, 1982, within the time period specified by the action  
1 2 statement. An investigation is presently being conducted into the trip of Breaker  
1 3 1C16Y. A Supplemental Report will be submitted upon resolution of the problem.  
1 4

FACILITY STATUS		% POWER		OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION	
1	5	E	28	1	0	0	29	N/A	30
ACTIVITY CONTENT		RELEASED OF RELEASE		AMOUNT OF ACTIVITY		LOCATION OF RELEASE			
1	6	Z	33	Z	34	N/A	35	36	

PERSONNEL EXPOSURES									
NUMBER				TYPE	DESCRIPTION				
1	7	0	0	0	37	Z	38	N/A	39

PERSONNEL INJURIES		
NUMBER	DESCRIPTION	(41)
0 0 0	N/A	

7 8 9 10 11 12  
LOSS OF OR DAMAGE TO FACILITY (43)  
TYPE DESCRIPTION  
1 9 Z (42) N/A

7 8 9 10  
PUBLICATION ISSUED DESCRIPTION (45) N/A  
(2) (0) (N) (44)  
7 8 9 10 68 69 80  
NRC USE ONLY

NAME OF PREPARER R. Frahm

PHONE: (609) 541-5900 629

8207300145 820721  
PDR ADCK 05000272  
C PDR