

CONTROL BLOCK: 

--	--	--	--	--	--	--

 (1)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

0 1 M D C C N 1 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5

LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT

CON'T

7 8 60 61 68 69 74 75 80

REPORT SOURCE DOCKET NUMBER EVENT DATE REPORT DATE

0 1 L 6 0 5 0 0 0 3 1 7 7 0 7 0 1 8 2 8 0 7 3 0 8 2 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | While in Mode 2 at 1530, it was discovered that 11B safety injection  
0 3 | tank (SIT) level transmitter (1-LT-321) was out of calibration to the  
0 4 | extent that the SIT level may have been outside T.S. 3.5.1.b limits,  
0 5 | consequently, the tank was declared inoperable. While the transmitter  
0 6 | was being replaced, the plant entered Mode 3 with pressurizer pressure  
0 7 | 1750 PSIA on 7-2-82. This terminating the action statement. There  
0 8 | are no similar events.

09		SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE				COMP. SUBCODE		VALVE SUBCODE					
7	8	S	F	X		Z		I	N	S	T	R	U	T	Z				
(17)		EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.									
LER/RO REPORT NUMBER		8	2	039		03		L		0									
ACTION TAKEN		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER					
C	H	Z		Z		0	0	0	0	N		Y		N		F	1	2	0
33	34	35		36		37	38	39	40	41		42		43		44	45	46	47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | Replaced 1-LT-321 (F&P #10B2496BBABDB) with a spare since harsh temper-  
1 1 | ature conditions made repairs difficult. The bad LT was found to have a  
1 2 | sero shift. The LT was recalibrated and returned to stock. All instru-  
1 3 | ment technicians will be informed of this event.  
1 4 |

1		5		C		28		0		0		0		29		N/A		30		A		31		Operator Observation		32	
7	8	9							10	11	12	13						44		45		46					80

ACTIVITY CONTENT  
RELEASED OF RELEASE

1	6	Z	(33)	Z	(34)
7	8	9	10	11	

AMOUNT OF ACTIVITY (35)  
N/A

LOCATION OF RELEASE (36)  
N/A

PERSONNEL EXPOSURES									
NUMBER			TYPE	DESCRIPTION					
1	7	000	Z	N/A					

PERSONNEL INJURIES		NUMBER		DESCRIPTION	
1	2	3	4	5	6
0	0	0	0	40	N/A

1		2		3		4		5		6		7		8		9		10		11		12		13		14		15		16		17		18		19		20		21		22		23		24		25		26		27		28		29		30		31		32		33		34		35		36		37		38		39		40		41		42		43		44		45		46		47		48		49		50		51		52		53		54		55		56		57		58		59		60		61		62		63		64		65		66		67		68		69		70		71		72		73		74		75		76		77		78		79		80		81		82		83		84		85		86		87		88		89		90		91		92		93		94		95		96		97		98		99		100	
1		2		3		4		5		6		7		8		9		10		11		12		13		14		15		16		17		18		19		20		21		22		23		24		25		26		27		28		29		30		31		32		33		34		35		36		37		38		39		40		41		42		43		44		45		46		47		48		49		50		51		52		53		54		55		56		57		58		59		60		61		62		63		64		65		66		67		68		69		70		71		72		73		74		75		76		77		78		79		80		81		82		83		84		85		86		87		88		89		90		91		92		93		94		95		96		97		98		99		100	

8 9 10  
PUBLICITY  
ISSUED DESCRIPTION (45) 8208090045 820730  
2 0 N (44) N/A PDR ADOCK 05000317  
S PDR  
NRC USE ONLY

NAME OF PREPARER G. S. Pavis/L. F. Basso

PHONE: 301-269-4742/4933