



MISSISSIPPI POWER & LIGHT COMPANY

Helping Build Mississippi

P. O. BOX 1640, JACKSON, MISSISSIPPI 39205

August 4, 1982

NORRIS L. STAMPLEY
SENIOR VICE PRESIDENT

Office of Inspection & Enforcement
U.S. Nuclear Regulatory Commission
Region II
101 Marietta St., N.W., Suite 3100
Atlanta, Georgia 30303

Attention: Mr. J. P. O'Reilly, Regional Administrator

Dear Mr. O'Reilly:

SUBJECT: Grand Gulf Nuclear Station
Unit 1
Docket No. 50-416
License No. NPF-13
File 0260/L-835.0
ECCS Actuation Instrumentation
Channel Failure
Reference: LER 82-013/03 L-0
AECM-82/450

On July 7, 1982, during a monthly functional test, it was determined that the ECCS actuation instrumentation channel had failed. Attached is LER 82-013/03 L-0.

Yours truly,

NLS:lm
Attachment

cc: Mr. R. B. McGehee (w/o)
Mr. T. B. Conner (w/o)
Mr. G. B. Taylor (w/o)

Mr. Richard C. DeYoung, Director (w/a)
Office of Inspection & Enforcement
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Document Control Desk (w/a)
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

8208090147 820804
PDR ADDCK 05000416
S PDR

AEIN7

OFFICIAL COPY

IE 22